






RC-RKPA™ Rack Mount System

INCLUDED PART LIST


- No. 1** RC-RKPA Power Supply Cradle, 801-1333 (Qty 1)
- No. 2** RC-RKPA L-Bracket, 802-1333 (Qty 1) or
RC-RKPA2 L-Bracket, 804-1333 (Qty 1)
- No. 3** RKPA-BRKT Wall Mount L-Bracket, 803-1333 (Qty 2)
- No. 4** 8-32 x 5/16", Phillips Flat Head Screw, 860-0070 (Qty 4)
- No. 5** 10/32 x 7/8" Phillips Pan Head Screw, 860-0073 (Qty 4)

PARTS NOT INCLUDED

- No. 6** RX Module (model varies)

ASSEMBLY INSTRUCTIONS

STEP 1: Attach Power Supply Cradle (**No. 1, Qty 1**) and L-Bracket (**No. 2, Qty 1**) to RX Module (**No. 6, Qty 1**) using 8-32 x 5/16" Phillips Flat Head Screws (**No. 4, Qty 4**).



STEP 2 (Optional): If mounting to wall, attach RKPA-BRKT Wall Mount L-Bracket (**No. 3, Qty 2**) using 10/32 x 7/8" Pan Head Screws (**No. 5, Qty 4**). Secure to wall with appropriate screws (not provided).

